

Subaru Pull Type Clutch Shudder

Ref: TN066

Issue date: Dec 2013

Issue number: 1

Important Information

Before fitment of new clutch, inspect clutch fork contacts for wear as shown in diagram below & replace, if necessary, with EXEDY Part No. CF02

Failure to do so may result in clutch shudder during operation of new clutch.

